



Photo 1: View from the southeast corner of the property. A capped well and pump are located in the center of the property.



Photo 2: View from Rt. 20 looking east towards a housing complex adjacent to the property.



Photo 3: View from the northeast corner of the property, looking toward Fishing Creek. The property has been filled to a surface elevation several feet higher than surrounding areas.



Photo 4: View from the northwest corner of the property, looking towards Fishing Creek. A pile of bricks is shown in the center of the photo.





Photo 5: View of Fishing Creek and the southern boundary of the property, looking towards the west.



Photo 6: View of Fishing Creek, and the railroad bed south of the creek.